

**Question: “(Why is there a) Lack of an Alarm Response Procedure for ENRAF in annulus in alarm”**

There is, and has been, an established Alarm Response Procedure (ARP) for the ENRAF system.

If this question is referring to a stop-work called by a tank farm worker late in the morning of Sept.27, 2012, the appropriate procedure was in place and implemented correctly by employees. The questioning worker was briefed on the existing alarm response procedure and the stop-work was lifted later that afternoon.

Our workers are highly trained, highly skilled and highly motivated to work safely. WRPS workers are encouraged to have a questioning attitude and to stop work if they don't understand the procedures.